

## FIRMWARE VERSION INFORMATION

Model: Barcode Printer Drivers for CUPS

Ref. No.: SVO23C1011

Date: Feb. 22, 2023

Revised:

Page: 1 of 1

	Revision	R1	R2	R3	R4
	Release	Jun., 2018	Mar., 2019	Dec., 2022	
	Serial No.	-----	-----	-----	
File	Version	V2.04	V2.09	V3.00	V4.00
	Part No.	-----	-----	-----	-----
	ROM Type	-----	-----	-----	-----
	Checksum	-----	-----	-----	-----
	Reason of Alteration	-----	A	B, C	B, C
	Label	Barcode Printer Drivers for CUPS V2.04 29th Jun 2018	Barcode Printer Drivers for CUPS V2.09 22nd Mar 2019	Barcode Printer Drivers for CUPS V3.00 15th Dec 2022	Barcode Printer Drivers for CUPS V4.00 24th Feb 2023
Description		Newly release  #EFE-23722 29-June-2018	Change, correction and addition have been made as below. · BA410T and BA420T have been added. · The resolution fine adjustment function has been  #EFE-24251 22-March-2019	Change, correction and addition have been made as below. · Some setting items have been added and some setting ranges have been modified. (for MacOS only)  #JKA-10131 13-December-2022	Change, correction and addition have been made as below. · Some setting items have been added and some setting ranges have been modified. (for LinuxOS only)  #JKA-10143 24-February-2023

Reason of Alteration

A: Additional new model

B: Keep higher quality

C: Alteration of Specifications

D: Standardization

E: Customer's Request

鈴木 享

Checked by: S. Suzuki

Y. Ogihara

Approved by: Y. Ogihara, Manager

## Attachment

### V2.04

Newly released

Applicable models:

BV410D, BV420D, BV410T, BV420T, B-EX4T1, B-EX4T2, B-852, B-852-R, B-FP2D, B-FP3D

#EFE-23722 29-June-2018

### V2.09

- BA410T and BA420T have been added to the applicable models.
- The resolution fine adjustment function has been added as below.
  - B-EX4 series: -20 to 10
  - BA400T series: -10 to 10

#EFE-24251 22-March-2019

### V3.0

**Change, correction and addition have been made as below.**

- To be used for multiple models in common, some setting items have been added and some setting ranges have been modified. (for MacOS only)
- The following restrictions have been added to the manual.
  - Do not perform printing of a job whose size exceeds the reception buffer of the printer. An error will occur in the printer or it does not operation properly.

#JKA-10131 15-December-2022

### V4.0

**Change, correction and addition have been made as below.**

- To be used for multiple models in common, some setting items have been added and some setting ranges have been modified. (for LinuxOS only)

#JKA-10143 24-February-2023